Tenney ENVIRONMENTAL

Reach-In Chamber Temperature & Humidity Capabilities



- Relative humidity range for custom reach-in chambers with air dryer and refrigeration modifications as needed.
- Relative humidity range for standard reach-in chambers limited by a 5°C dew point temperature.
- Optional special sensor suggested for long-term testing in this range.
- Relative humidity range for standard reach-in chambers with air dryer.