






Walk-In Chamber Temperature & Humidity Capabilities



-  Relative humidity range for custom walk-in chambers with air dryer and refrigeration modifications as needed.
-  Relative humidity range for standard walk-in chambers limited by a 5°C dew point temperature.
-  Optional special sensor suggested for long-term testing in this range.
-  Relative humidity range for standard walk-in chambers with air dryer.